



03500.016000

ccf
PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:)
: Examiner: K. Quarterman
NORITAKA MOCHIZUKI, ET AL.)
: Group Art Unit: 2879
Application No.: 09/993,672)
:
Filed: November 27, 2001)
:
For: DISPLAY DEVICE HAVING) January 25, 2006
CONICAL TRANSPARENT)
MEMBERS COVERING ELECTRO-)
LUMINESCENT ELEMENTS)
:
U.S. Patent No. 6,858,983 B2)
:
Issued: February 22, 2005)

Certificate
JAN 27 2006
of Correction

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

31/26/2006 SZEWDIE1 00000004 6858983

Q1 FC:1811

100.00 OP

REQUEST FOR
CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:


It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes and mistakes which are not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

JAN 30 2006

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction. Any additional fee required by this paper may be charged to Deposit Account No. 06-1205.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our below-listed address.

Respectfully submitted,



Scott D. Malpede
Attorney for Patentees
Registration No. 32,533

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

SDM/vmm

DC_MAIN 202411v1

JAN 30 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,858,983 B2

DATED : February 22, 2005

INVENTOR(S) : NORITAKA MOCHIZUKI, ET AL.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

[56] REFERENCES CITED:

FOREIGN PATENT DOCUMENTS, "03152898" should read --3-152898--.

COLUMN 7:

Line 22, "semispherical" should read --hemispherical--.

Line 52, "semispherical" should read --hemispherical--.

Line 61, "semispherical" should read --hemispherical--.

COLUMN 14:

Line 21, "S" should read --P--.

DC_MAIN 202409v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,858,983 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)
(Form#30)



JAN 30 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,858,983 B2

DATED : February 22, 2005

INVENTOR(S) : NORITAKA MOCHIZUKI, ET AL.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

[56] REFERENCES CITED:

FOREIGN PATENT DOCUMENTS, "03152898" should read --3-152898--.

COLUMN 7:

Line 22, "semispherical" should read --hemispherical--.

Line 52, "semispherical" should read --hemispherical--.

Line 61, "semispherical" should read --hemispherical--.

COLUMN 14:

Line 21, "S" should read --P--.

DC_MAIN 202409v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,858,983 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)
(Form#30)



JAN 30 2006